
Geryville Pike | Key Issues





Corridor-Wide Issues

- Several skewed intersections with cross-streets
- Constrained right-of-way with structures close to roadway
- Through-traffic diverting from Lansdale and Quakertown PA Turnpike interchanges
- Desire for increased pedestrian and bicycle connections and crossings
- Roadway geometry and drainage issues require increased winter maintenance

Intersection with Old School Road


• Skewed intersection

Between Brinkman Road and Campbell Road

Poor drainage leads to water pooling and icy winter conditions

Intersection with Hendricks Road

• Limited sight distance due to vertical curve



Intersection with PA 663

- Safety concerns
- Need for additional capacity

Intersection with Buck Road

• Limited sight distance, particularly from Buck Road

Intersection with James Road

- Sharp horizontal curve and unusual configuration at the closely spaced intersections with James Road and St Pauls Church Road
- Crash density higher than corridor average

Legend

Geryville Pike

Bridges

Traffic Signals

Intersecting Road Ownership


PennDOT

—— Local Roads

Municipal Boundaries

Geryville Pike | Key Issues





Corridor-Wide Issues

- Several skewed intersections with cross-streets
- Constrained right-of-way with structures close to roadway
- Through-traffic diverting from Lansdale and Quakertown PA Turnpike interchanges
- Desire for increased pedestrian and bicycle connections and crossings
- Roadway geometry and drainage issues require increased winter maintenance

Intersection with Swamp Creek Road

- Poor drainage leads to water pooling in the roadway
- Roadway flooding occurs due to nearby Unami Creek
- Lack of pedestrian connections between Sumneytown Village and Unami Creek

Intersection with Sumneytown Pike

- Cross-traffic vehicle speeds on Sumneytown Pike
- Lack of access management at Sumneytown Hotel
- Sumneytown Village is a desirable destination and place for walking
- Limited space for expanded infrastructure due to historic nature and buildings close to the roadway



Intersection with Hiffletrayer Road

Crash density higher than corridor average

Woodridge Drive to Magazine Road

• Safety concerns due to steep grades and sharp curves, particularly with winter weather conditions

Legend Geryville Pike Bridges Traffic Signals Intersecting Road Ownership PennDOT Local Roads Municipal Boundaries